


Bolt connection as close as possible to the center of the bracket



AD_RT_RL_RF	Assembly Details - Roof Top Railless Ridge Fix
A Brewis	
Revision 1	
June 2022	